

# FLEX & FLOCK

## For Textiles

GRAFIFLEX and Grafiflock are computer cut materials for application onto items such as T-shirts, flags, banners, work wear and caps, an ideal way to promote your company.

### Transfer Instructions

After cutting in REVERSE heat apply the material with its own acetate backing at:

GRAFIFLOCK: Temperature: 160/170 °C  
Time: ± 15-20 sec.

GRAFIFLEX: Temperature: 150/160 °C  
Time: ± 10-15 sec.

All values should be considered as approximate indications!

### Durability:

The durability of Grafiflock/Grafiflex when transferred onto textiles depends on the textile cleaning treatment. It is advisable to wash Grafiflock at a max. 40 °C and Grafiflex at a max. 60°C.